

# Grasshoppers

Use the "third hand" to steady parts for tack welding. Safe and convenient!



# PAUWELS

gassen, lassen & gereedschappen

## MAGNETIC GRASSHOPPERS

- Spring-loaded arm self-adjusts for REPETITIOUS WORK HOLDING.
  - New Copper Spindle (deluxe model).
  - Adjustable V-Pad Base adapts to: round, square, flat, and angled surfaces.
- Anti-tipping Bolt provides stability.

STRONG HAND TOOLS  
PATENT PENDING  
All Rights Reserved.




NEW ITEM

Feature	Magnetic V-Pad Base	Anti-tipping Bolt	Max. OAL (mm)	Width x Height (mm)	Weight (kg)
Copper Spindle	✓	✓	190	64 x 88	0.4
Copper Spindle	✓	✓	250	100 x 115	0.8
Brass Contact	✓	✓	203	64 x 76	0.3
Brass Contact	✓	✓	234	100 x 100	0.6

⚠ Must be used for tack welding only and removed before completing weld. Avoid prolonged exposure of magnetic products to heat sources of 176°F / 80°C.


## STANDARD GRASSHOPPERS



STRONG HAND TOOLS  
PATENTED  
ALL RIGHTS RESERVED.



Demo Video



Part No.	Product Includes	Max. OAL (mm)	Width x Height (mm)	Weight (kg)
P980001347	Three Brass Contacts, Copper Ribbon, Spring Clip Attachment	300	114 x 102	0.7
P980001346	Brass Contact	300	114 x 102	0.7